KB5TX Repeater site

Quick Tour of site and Winter Storm Damage

Third week of February 2021

Marsh Pronneke WA5UBO

Location from Boerne



Entry Road to access the Repeater Site



Approaching Site



Front of Building




Front



Back Side



Base of Mono-Pole Tower




Look see up the tower



Inside Building Before Rebuild




Rotted Paneling from Water Intrusion



Rotted Paneling



Floor



Floor



Floor Rotting at Door Threshold



Sole Plate or What Sole Plate?



Removing Rotted Subfloor



More Sub Floor Removed



Rotten Studs from Water




Doorway Threshold Rot




Corroded Electric Connections



Roof Condition



Closeup of Roof



Current Roof Condition



Installing New Subfloor



Rear Rebuilt Wall Sill Plate and Floor



Hardline Entry Point to Building



Hardline Entry Point Detail




Proper Feed Line Entry Panel & Boots




New 7/16 Plywood Walls & Floor Painting



West Wall With Ground Buss



Real Ground Buss




Duplexer Cabinet and Equipment Rack




Both Yaesu Fusion Repeaters



Demark Board



Demark & Power Distribution



Wacom Duplexer




Is it a Thiefe?





Aerial View of Tower & Building



Up Close at Top of Tower Courtesy of Mark N5YZV & his Drone



2-14-2021 Winter Storm Camera View



Camera View 2-17-21



View



Damage at Repeater Site View up Tower



View of Old DB-224 Antenna



Closeup of DB-224 at 45 deg angle



Air Conditioner Awing



Side View From Ice Damage



Special Thanks

- Thanks to these members that helped when needed.
 - Stephen Schwarz KA5WJY
 - Greg Stone AB5I
 - Ron Wood KF5SIJ
 - Mark Seamans N5YZV & Drone & Internet
 - Steve Lazar W5SCL
 - Gerry Nunan K2HIG
 - Rodney Vorndam K9ROD
 - Don Udel KI5AIU
 - Ben Koerner K5AYR